## **Reflective Cracking Construction Notes**

**Date:** January 20, 2015

**Project:** Reflective Cracking Indoor Phase IV

## Weather:

· · · · · · · · · · · · · · · · · · ·		
	6:54 AM	3:54 PM
Temperature (°F):	26.1	44.1
Dew Point (°F):	23.0	27.0
Humidity (%):	88	51
Visibility (Miles):	10.0	10.0
Wind (MPH):	3.5 NW	6.9 WNW
Conditions:	Clear	Overcast

**Working Hours:** 7:00 AM – 4:30 PM

**Sub-Contractor(s):** ARA, Advanced Fluid Systems (AFS)

**Personnel:** (1) technician (ARA), (1) supervisor, (1) technician (AFS)

**Equipment:** Hand tools

## **Reflective Cracking Construction Notes:**

AFS met with FAA and SRA personnel in the morning to discuss the rig movement incident that occurred on 1/14/2015. AFS then examined the rig motion control system, including the MTS position sensors, to evaluate the system and troubleshoot any possible malfunctions that could have caused the movement incident.